## INTERACTIVE ENVIRONMENTAL COMPLIANCE CORPORATION

3410 Creekview Drive Bonita Springs, FL 34134 PHONE (631) 513-1558 FAX (239) 949-4831

February 10, 2012

Office of Enforcement and Compliance Assurance
Office of Federal Activities
International Compliance Assurance Division (2254A)
Environmental Protection Agency
1200 Pennsylvania Ave., NW.
Washington, DC 20460.

Re:

C&C Metal Products Corp.

EPA ID# NJD001717040

456 Nordhoff Place. Englewood, NJ 07631

Dear Sirs:

This letter is written because the above named facility is an exporter of hazardous waste. Below is a description of the hazardous waste that was exported and manifested in 2011:

 RQ Waste Environmentally Hazardous Substance Solid n.o.s.(Copper, Nickel, Zinc) Class 9, UN3077 PG III, F006

\*5343 pounds on 2/17/11


\*8351 pounds on 8/16/11

The amount of F006 waste exported in 2011 was 13,694 pounds.

2. RQ Waste cyanides, inorganic, solid, n.o.s. (brass, copper) Class 6.1, UN 1588, PG II, F009

\*9145 pounds on 2/17/11

The total amount of waste exported in 2011 was 22,839 pounds.



≀oute

**EPA Mail** 

To: US EPA

Mailstop:

ARIEL RIOS SOUTH

Department:

2310A

Phone:

PKG Condition Certified

70072560000217917170

[.]..[...[h..][.]...[h..][h..]

1 pos fendsylania me

DYLY 1851 5000 0325 5005



CERTIFIED MAIL

PLACE STICKER AT TOP OF ENVELOPE TO THE RIGHT OF THE RETURN ADDRESS, FOLD AT DOTTED LINE





All of the above noted waste was sent to the following facility for treatment:

Stablex Canada Inc. 760 Industrial Blvd.

EPA ID# NYD980756415

760 Industrial Blvd.

Blainville, Quebec Canada J7C 3V4

## **Transporters**

Transport Rollex Ltee 910 Lionel-Boulet Blvd. Varennes, QC J3X 1T6 EPA ID# NYF006000053

## Waste Minimization

The following conditions have contributed to the decreased amount of waste generated over the past few years:

- We have increased the amount of rinse cycles on the plating baths to decrease the amount of waste generated from the plating lines.
- Nickel and cyanide are collected in dragout tanks and transferred back into the plating baths which has decreased the amount of hazardous waste generated.
- 3. The waste is dried before shipping to decrease the total volume of the hazardous waste.
- 4. Over the past year most of the plating operations have been moved back to the facility in New Jersey.

"I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment."

Sincerely,

Sherry Schirripa Consultant

approved by:

Willie Clark, Operations Manager, C&C Metal Products Corp.